

Declassification Review by  
NGA/DoD**SECRET**

CIA-2

OUT 52550

100 DEC 31 01 22Z

P 302319Z

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUCVAB/4080 STRAT WG, OL 19, BARKSDALE AFB, LA

RUCVAB/2D RTS, BARKSDALE AFB, LA

RUEAHQ/DIAXX

RUECYG/NAVY PIC

RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF

RUWGAA/2AF, BARKSDALE AFB, LA

DA GRNC

BT

**SECRET**

CITE CIA-Z-1097

15TH AF (FOR DI), SAC (FOR DIM, GOLDEN TREE, DOCR, DM 4) 2D AF  
(FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B 13 WAS USED IN MISSION 3802 FLOWN ON 28 DECEMBER  
1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: A PLUS DENSITY STREAK, LOCATED APPROXIMATELY  
3.40" FROM AND ROUGHLY PARALLEL TO THE INBOARD EDGE OF THE FILM,  
IS PRESENT FROM HEAD TO TAIL. TWO CONTINUOUS, WAVERING MINUS  
DENSITY STREAKS ARE PRESENT IN THE VICINITY OF THE OUTBOARD EDGES  
OF THE FORMATS THROUGHOUT 75 PERCENT OF THE MATERIAL. SMALL  
TEARS, REPAIRED AT THE PROCESSING SITE, ARE NOTED ON THE INBOARD  
EDGE OF FRAME 1046. SEVERE EDGE-TO-EDGE TEARS DAMAGED FRAME 1047  
AND WERE REPAIRED AT THE PROCESSING SITE WITH HEAT SPLICES AND  
TRANSPARENT TAPE. PINHOLES APPEAR INTERMITTENTLY IN THE VICINITY  
OF THE INBOARD EDGE OF THE FILM. HEAVY CONCENTRATIONS OF PINHOLES  
APPEAR IN A NUMBER OF FRAMES. EXAMPLES: FRAMES 111, 552, 553,  
653, 782, 783, 898, 911, 922 AND 1102. EDGE-TO-EDGE LIGHT LEAKS

**SECRET**

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

-PAGE 2-

DEGRADE FRAMES 1048 AND 1049. FRAMES 1045, 1163, AND 1664 CONTAIN BLISTERS. HEAT SPLICES ARE LOCATED BETWEEN FRAMES 671/672, 1037/1038 AND 1040/1041. A HEAT SPLICE IS LOCATED WITHIN THE FORMAT OF FRAME 1141 AND MANUFACTURER'S SPLICES ARE LOCATED IN FRAMES 27 AND 1318. PART 9 (FRAMES 1065-1167) WAS SPOOLED TAIL OUT.

C. THE FIRST 107 FRAMES CONTAIN A SERIES OF MINUS DENSITY DOTS SPACED 1.5" APART AND 2.7" FROM THE OUTBOARD EDGE. FORMAT FRAME REFLECTION IS PRESENT AT THE OUTBOARD AND DATA BLOCK EDGES THROUGHOUT THE MISSION. NUMEROUS PINHOLES OCCUR IN FRAMES 1072 TO 1078. FRAME 1068 CONTAINS A MANUFACTURER'S SPLICE WHILE HEAT SPLICES ARE LOCATED IN FRAMES 551 AND 1380.

D. BOTH SIDES: THERE ARE 2274 TITLED FRAMES ON EACH SIDE OF THE MISSION.

E. THERE WERE NO MAJOR PROCESSING ANOMALIES OR CAMERA MALFUNCTIONS IN THIS MISSION.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 40 PERCENT OF THIS MISSION.

S E C R E T

/END OF MESSAGE/

(ABOVE MESSAGE ALSO SENT CIA WATCH OFFICE (CGS))